



SRI MANAKULA VINAYAGAR ENGINEERING COLLEGE

(Approved by AICTE, New Delhi & Affiliated to Pondicherry University)
 (Accredited by NBA-AICTE, New Delhi, ISO 9001:2000 Certified Institution &
 Accredited by NAAC with "A" Grade)
 Madagadipet, Puducherry - 605 107



DEPARTMENT OF MECHANICAL ENGINEERING

Subject Name: Electrical and Electronics Engineering

Subject Code: MET35

Prepared by:

Dr.K.Suresh, Professor / EEE
 Mr.B.Parthiban, Assistant Professor / EEE
 Mr.R.Ragupathy, Assistant Professor/ EEE

Verified by:

Approved by:

2. AC MACHINES

Theory and operation of 3 phase Induction motor - constructional details – starting methods – speed control methods – principle of operation of single phase Induction motor – stepper motor – AC series motor – Applications

Part-A (2 Marks)

1. **What is the function of capacitor in a single phase induction motor** (NOV/2014)
 - Developing high starting torque
 - To improve the power factor
2. **What are the classifications of three phase induction motor based on the method of construction** (NOV/2014)

The three phase induction motor are classified based on their constructions are

 - Squirrel cage induction motor
 - Slip ring (or) wound rotor induction motor
3. **What is Slip?** (APRIL/2014)

(or)

Define slip of an induction motor. (APRIL/2012)

Slip of the induction motor is defined as the "**Difference between the synchronous speed (N_s) and actual speed of rotor i.e. motor (N) expressed as a fraction of the synchronous speed (N_s)**". This is also called **absolute slip fractional slip** and is denoted as 's'

Thus
$$s = \frac{N_s - N}{N_s}$$
 ----- Absolute slip

The percentage slip is expressed as,

$$\% s = \frac{N_s - N}{N_s} * 100$$
 ----- Percentage slip

4. **Mention the methods available to make single phase induction motors self-starting** (APRIL/2014)

(or)

What are the classifications of single phase induction motor based on the method of starting (NOV/2012)

(Or)

What are the different types of single phase induction motor? (APRIL/2012)

- Split phase induction motor
- Capacitor start induction motor
- Capacitor start and capacitor run induction motor
- Shaded pole induction motor

5. A 6 pole, 50 Hz, three phase induction motor runs at 800 rpm at full load. Determine the value of slip at this load condition. (NOV/2013)

$$P = 6$$

$$F = 50 \text{ Hz}$$

$$N = 800 \text{ rpm}$$

$$N_s = \frac{120 f}{P}$$

$$N_s = \frac{120 * 50}{6} = 1000 \text{ rpm}$$

$$\% s = \frac{N_s - N}{N_s} * 100$$

$$\% s = \frac{1000 - 800}{1000} * 100$$

$$\% s = 20 \%$$

6. Mention some applications of AC series motor (NOV/2013)

- Electric traction
- Hoists
- Locomotives

7. What are the advantages of three phase induction motor? (APRIL/2013)

- Simple and Rugged construction
- High efficiency
- Self-starting motor
- Good power factor
- High reliable
- Requires less maintenance
- Low cost
- Can be operated in explosive and in dirty environment

8. Mention the types of stepper motor. (APRIL/2013)

- Variable reluctance stepper motor
- Permanent magnet stepper motor
- Hybrid stepper motor

9. Compare squirrel cage rotor and slip ring rotor. (NOV/2012)

| S. NO. | SLIP RING INDUCTION ROTOR | SQUIRREL CAGE ROTOR |
|--------|--|---|
| 1 | Rotor consists of three windings similar to stator winding | Rotor consists of bars which are shorted at the ends with the help of end rings |
| 2 | Construction is complicated | Construction is simple |
| 3 | Resistance can be added externally | Resistance cannot be added externally |
| 4 | Slip rings and brushes are present to add external resistance | Slip rings and brushes are absent |
| 5 | The construction is delicate and due to brushes, frequent maintenance is necessary | The construction is robust and maintenance free |

| | | |
|----|---|---|
| 6 | The rotors are very costly | Rotor is cheap |
| 7 | Only 5% of induction motors in industry use slip ring rotor | Very commonly used motor in industry |
| 8 | High starting torque can be obtained | Moderate starting torque can be obtained |
| 9 | Speed control is possible | Speed control is not possible as it has short circuit rotor |
| 10 | Less efficiency | High efficiency |

10. What are the main parts of an induction motor

- Stator (Stationary parts)
- Rotor (Rotating parts)

(Part- B) 11 Marks

1. With neat sketches explain the constructional details and operation of three phase induction motor. (APRIL/2013)

(or)

Explain the construction of a three phase induction motor with neat sketch.

CONSTRUCTION OF THREE PHASE INDUCTION MOTOR


Basically the induction motor (all motors) consists of two main parts, namely

- STATOR
- ROTOR

The conversion of electrical power to mechanical power takes place in a rotor. Hence a rotor develops a driving torque and rotates.

STATOR:

The stator has a laminated type of construction made up of stampings which are 0.4 to 0.5 mm thick. The stampings are slotted in inner periphery to carry the stator winding. The stampings are insulated from each other. Such a construction essentially keeps the iron losses to a minimum value. The number of stampings are stamped together to build the stator core. The built-up core is then fitted in a casted or fabricated steel frame. The choice of material for the stampings is generally silicon steel, which minimizes the hysteresis loss. The slots in the periphery of the stator core carry a three-phase winding, connected either in star or delta. This three-phase winding is called stator winding. It is wound for a definite number of poles. This winding when excited by a three-phase supply produces a magnetic rotating field as discussed earlier. The choice of number of poles depends on the speed of the rotating magnetic field required. The radial ducts are provided for the cooling purpose. In some cases, all the six terminals of three-phase stator winding are brought out which gives flexibility to the user to connect them either in star or delta.



Stator core


ROTOR:

The rotor is placed inside the stator. The rotor core is also laminated in construction and uses cast iron. It is cylindrical, with slots on its outer periphery. The rotor conductors or winding is placed in the rotor slots. The two types of rotor constructions which are used for induction motors are,


- Squirrel cage rotor and
- Slip ring wound rotor

Squirrel Cage Rotor

The rotor core is cylindrical and slotted on its periphery. The rotor consists of un-insulated copper or aluminum bars called **rotor conductors**. The bars are placed in the slots. These bars are permanently shorted at each end with the help of conducting copper ring called **endring**. The bars are usually brazed to the endring to provide good mechanical strength. The entire structure looks like a cage, forming a closed electrical circuit. So the rotor is called squirrel cage rotor. The construction is shown in the below figures.



(a) Cage type structure of rotor




(b) Symbolic representation

Squirrel cage rotor

As the bars are permanently shorted to each other through endring, the entire rotor resistance is very small. Hence this rotor is also called **short circuited rotor**. As rotor itself is short circuited, no external resistance can have any effect on the rotor resistance. Hence no external resistance can be introduced in the rotor circuit. So slip ring and brush assembly is not required for this rotor. Hence the construction of this rotor is very simple. The air gap between stator and rotor is kept uniform and as small as possible.

In this type of rotor, the slots are not arranged parallel to the shaft axis but are skewed as shown in the below figure.




Skewing in rotor construction

The skewing is done in the squirrel cage rotor to

- Reduce humming noise hence skewing makes the motor operation quite.
- Make the rotor operation smooth.
- Avoid magnetic locking between stator and rotor teeth
- Increases the effective transformation ratio between stator and rotor.

Slip Ring Rotor Wound Rotor

In this type of construction, rotor winding is exactly similar to the stator. The rotor carries a three phase star or delta connected, distributed winding, wound for same number of poles as that of stator. The rotor construction is laminated and slotted. The slots contain the rotor winding. The three ends of three phase winding, available after connecting the winding in star or delta, are permanently connected to the slip rings. The slip rings are mounted on the same shaft. We have seen that slip rings are used to connect external stationary circuit to the internal rotating circuit. So in this type of rotor, the external resistance can be added with the help of brushes and slip ring arrangement, in series with each phase of the rotor winding.



Slip rings or wound rotor construction

In the running condition, the slip rings are shorted. This is possible by connecting a metal collar which gets pushed and connects all the slip rings together, shorting them. At the same time brushes are also lifted from the slip rings. This avoids wear and tear of the brushes due to friction. The possibility of addition of an external resistance in series with the rotor, with the help of slip rings is the main feature of this type of rotor.

WORKING PRINCIPLE OF THREE PHASE INDUCTION MOTOR

Induction motor works on the principle of Faraday's Law of Electromagnetic induction. When a three-phase supply is given to the three-phase stator winding, a rotating magnetic field of constant magnitude will be produced. The speed of this rotating magnetic field is synchronous speed $N_{sr.p.m.}$


$$N_s = 120f/P$$

Where, f = supply frequency.

P = Number of poles for which stator winding is

wound.

This rotating field produces an effect of rotating poles around a rotor. Let the direction of rotation of this rotating magnetic field is clockwise as shown in the below figure (a).



Now at this instant rotor is stationary and stator flux R.M.F. is rotating. So it's obvious that there exists relative motion between the R.M.F. and rotor conductors. Now the R.M.F. gets cut by rotor conductors as R.M.F. sweeps over rotor conductors. Whenever a conductor cuts the flux, e.m.f. gets induced in it. So e.m.f. gets induced in the rotor conductors called rotor induced e.m.f. This is electromagnetic induction. As rotor forms a closed circuit, induced e.m.f. circulates current through rotor called rotor current as shown in the above figure (b).

Any current-carrying conductor produces its own flux. So rotor produces its flux called rotor flux. For assumed direction of rotor current, the direction of rotor flux is clockwise as shown in the above figure (c). This direction can be easily determined using the right-hand thumb rule. Now there are two fluxes, one R.M.F. and the other rotor flux. Both the fluxes interact with each other as shown in the below figure (d). On the left of the rotor conductor, two fluxes cancel each other to produce a low flux area. As flux lines act as stretched rubber bands, high flux density areas exert a push on the rotor conductor towards the low flux density area. So the rotor conductor experiences a force from left to right in this case, as shown in the below figure (d), due to the interaction of the two fluxes.

As all the rotor conductors experience a force, the overall rotor experiences a torque and starts rotating. So interaction of the two fluxes is very essential for motoring action. Hence rotor starts rotating in the same direction as that of rotating magnetic field.




Figure (d)

SLIP OF INDUCTION MOTOR

When the rotor rotates in the same direction as that of R.M.F. but in steady state attains a speed less than the synchronous speed. The difference between the two speeds i.e. synchronous speed of R.M.F. (N_s) and rotor speed (N) is called **slip speed**. This slip speed is generally expressed as the percentage of the synchronous speed.

So slip of the induction motor is defined as the “**Difference between the synchronous speed (N_s) and actual speed of rotor i.e. motor (N) expressed as a fraction of the synchronous speed (N_s)**”. This is also called **absolute slip** and is denoted as ‘ s ’

Thus

$$s = \frac{N_s - N}{N_s} \text{----- Absolute slip}$$

The percentage slip is expressed as,

$$\% s = \frac{N_s - N}{N_s} * 100 \text{----- Percentage slip}$$

In terms of slip, the actual speed of motor (N) can be expressed as, At

$$N = N_s(1 - s)$$

$s = 1$ ----- At start

At start, motor is at rest and hence its speed N is zero.

This is maximum value of slip possible for induction motor which occurs at start. While $s = 0$ given $N = N_s$ which is not possible for an induction motor. So slip of induction motor cannot be zero under any circumstances. Practically

motor operates in the slip range of 0.01 to 0.05 i.e. 1% to 5%. The slip corresponding to full load speed of the motor is called full load slip.

2. Derive the equation for torque developed by three phase induction motor. Draw the torque slip curve and deduce the condition for maximum torque (11)(NOV/2014)

TORQUE EQUATION:

“Torque is the turning force through a radius and the units is rated in Nm”

The torque produced in the induction motor depends on the following factors:

- The part of rotating magnetic field which reacts with rotor and is responsible to produce induced e.m.f. in rotor.
- The magnitude of rotor current in running condition.
- The power factor of the rotor circuit in running condition.

Mathematically the relationship can be expressed as

$$T \propto \Phi I_2 r \cos \Phi_2 \text{----- (1)}$$

Where, Φ = Flux responsible to produce induced e.m.f.

I_{2r} = Rotor running condition

$\cos \phi_{2r}$ = Running p.f. of motor

The flux Φ produced by stator is proportional to stator voltage.

$$\Phi \propto E_1 \quad \text{----- (2)}$$

While E_1 and E_2 are related to each other through ratio of stator turns to rotor turns i.e. K

$$\frac{E_2}{E_1} = K \quad \text{----- (3)}$$

Using equation (3) in (2) we can write,

$$E_2 \propto \Phi \quad \text{----- (4)}$$

Thus in equation (1), ϕ can be replaced by E_2

While
$$I_{2r} = \frac{E_{2r}}{Z_{2r}} = \frac{s E_{2r}}{\sqrt{R_2^2 + (sX_2)^2}} \quad \text{----- (5)}$$

And
$$\cos \phi_{2r} = \frac{R_2}{Z_{2r}} = \frac{R_2}{\sqrt{R_2^2 + (sX_2)^2}} \quad \text{----- (6)}$$

Using (4), (5), (6) in equation (1),

$$T \propto E_2 \frac{s E_{2r}}{\sqrt{R_2^2 + (sX_2)^2}} \frac{R_2}{\sqrt{R_2^2 + (sX_2)^2}}$$

$$T \propto \frac{s E_2^2 R_2}{R_2^2 + (sX_2)^2} \text{ N-m}$$

$$T = \frac{k s E_2^2 R_2}{R_2^2 + (sX_2)^2} \quad \text{----- (7)}$$

Where, k = Constant of proportionality

The constant k is proved to be $3/2\pi n_s$ for the three phase induction motor

$$k = \frac{3}{2\pi n_s} \quad \text{----- (8)}$$

n_s = synchronous speed in r.p.s. = $\frac{N_s}{60}$

Using (8) in (7) we get the torque equation as,

$$T = \frac{3}{2\pi n_s} \frac{s E_2^2 R_2}{R_2^2 + (sX_2)^2} \text{ N-m}$$

Sotorque developed at any load condition can be obtained if slip at that load is known and all standstill rotor parameters are known.

STARTING TORQUE

Starting torque is nothing but the torque produced by an induction motor at start. At start, $N=0$ and slip = 1. So putting $s=1$ in the torque equation we can write expression for the starting torque T_{st} ,

$$T_{st} = \frac{3}{2\pi n_s} * \frac{E_2^2 R_2}{R_2^2 + X_2^2} \text{ N-m}$$

The change in R_2 at start is possible in case of slip ring induction motor only. This is the principle used in case of slip induction motor to control the starting torque T_{st} .

CONDITION OF MAXIMUM TORQUE

It is clear that torque depends on slip at which motor is running. The supply voltage to the motor is usually rated and constant and there exists a fixed ratio between E_1 and E_2 . Hence E_2 is also constant. Similarly R_2, X_2 and n_s are constants for the induction motor. Hence while finding the condition for maximum torque, remember that the only parameter which controls the torque is slip s .

$$\frac{dT}{ds} = 0$$

where
$$T = \frac{k s E_2^2 R_2}{R_2^2 + (s X_2)^2}$$

While carrying out differentiation remember that E_2, R_2, X_2 and k are constants. The only variable is slip s . As load on motor changes, its speed changes and hence slip changes. This slip decides the torque produced corresponding to the load demand.

$$T = \frac{k s E_2^2 R_2}{R_2^2 + s^2 X_2^2} \quad \dots \text{writing } (s X_2)^2 = s^2 X_2^2$$

As both numerator and denominator contains s terms, differentiate T with respect to s using the rule of differentiation for u/v .

$$\therefore \frac{dT}{ds} = \frac{(k s E_2^2 R_2) \frac{d}{ds} (R_2^2 + s^2 X_2^2) - (R_2^2 + s^2 X_2^2) \frac{d}{ds} (k s E_2^2 R_2)}{(R_2^2 + s^2 X_2^2)^2} = 0$$

$$\therefore k s E_2^2 R_2 [2s X_2^2] - (R_2^2 + s^2 X_2^2) (k E_2^2 R_2) = 0$$

$$\therefore 2 s^2 k X_2^2 E_2^2 R_2 - R_2^2 k E_2^2 R_2 - k s^2 X_2^2 E_2^2 R_2 = 0$$

$$\therefore k s^2 X_2^2 E_2^2 R_2 - R_2^2 k X_2^2 R_2 = 0$$

$$s^2 X_2^2 - R_2^2 = 0 \quad \text{Taking } k E_2^2 R_2 \text{ common.}$$

$$s^2 = \frac{R_2^2}{X_2^2}$$

$$s = \frac{R_2}{X_2} \quad \text{Neglecting negative slip}$$

This is the slip at which the torque is maximum and is denoted as s_m .

$$s_m = \frac{R_2}{X_2}$$

It is the ratio of standstill per values of resistance and reactance of rotor, when the torque produced by the induction motor is at its maximum.

MAXIMUM TORQUE:

This can be obtained by substituting $s_m = R_2/X_2$ in the torque equation. It is denoted by T_m .

$$T_m = \frac{k s_m E_2^2 R_2}{R_2^2 + (s_m X_2)^2}$$

$$T_m = \frac{k \left(\frac{R_2}{X_2} \right) E_2^2 R_2}{R_2^2 + \left(\frac{R_2}{X_2} X_2 \right)^2}$$

$$T_m = \frac{k E_2^2}{2 X_2} \text{ N-m}$$

From the expression of T_m , it can be observed that

- It is inversely proportional to the rotor reactance.
- It is directly proportional to the square of the rotor induced e.m.f. at standstill.

The most interesting observation is, the maximum torque is not dependent on the rotor resistance R_2 . But the slip at which it occurs i.e. speed at which it occurs depends on the value of rotor resistance R_2 .

3. **Problem 1:** A 3 phase, 400V, 50Hz, 4 pole induction motor has star connected stator winding. The rotor resistance and reactance are 0.1Ω and 1Ω respectively. The full load speed is 1440 r.p.m. Calculate the torque developed on full load by the motor. Assume stator to rotor ratio as 2:1.

Solution:

The given values are,

$P=4$, $f=50$ Hz, $R_2=0.1\Omega$, $X_2=1\Omega$, $N=1440$ r.p.m. Stator turns/Rotor turns = 2/1

$$K = E_2/E_1 = \text{Rotor turns/Statorturns} = 1/2 = 0.5$$

$$N_s = 120f/P = 120 \times 50 / 4 = 1500 \text{ r.p.m.}$$

$$E_{1\text{line}} = 400 \text{ V}$$

$$E_{1\text{ph}} = E_{1\text{line}} / \sqrt{3} = 400 / \sqrt{3} = 230.94 \text{ V}$$

$$\text{But, } E_{2\text{ph}}/E_{1\text{ph}} = 0.5 = K$$

$$E_{2\text{ph}} = 0.5 \times 230.94 = 115.47 \text{ V}$$

$$\text{Full load slip, } s = (N_s - N)/N_s = (1500 - 1440)/1500 = 0.04$$

$$n_s = \text{Synchronous speed in r.p.s.}$$

$$= N_s/60 = 1500/60 = 25 \text{ r.p.s.}$$

$$T = \frac{3}{2\pi n_s} \frac{s E_2^2 R_2}{R_2^2 + (s X_2)^2}$$

$$T = \frac{3}{2\pi \times 25} \times \frac{0.04 \times (115.47)^2 \times 0.1}{(0.1)^2 + (0.04 \times 1)^2}$$

$$\mathbf{T = 87.81 \text{ N-m}}$$

4. **Problem 2:** A 400V, 4 pole, 3 phases, and 50 Hz star connected induction motor has rotor resistance and reactance per phase equal to 0.01Ω and 0.1Ω respectively. Determine i) Starting torque ii) slip at which maximum torque will occur iii) speed at which maximum torque will occur. Assume ratio of stator to rotor turns as 4.

Solution:

The given values are,

$P=4$, $f=50$ Hz, stator turns/ rotor turns = 4, $R_2=0.01\Omega$, $X_2=0.1\Omega$

$$E_{1\text{line}} = \text{stator line voltage} = 400 \text{ V}$$

$$E_{1\text{ph}} = E_{1\text{line}} / \sqrt{3} = 400 / \sqrt{3} = 230.94 \text{ V} \quad \dots \text{star connection}$$

$$K = E_{2\text{ph}}/E_{1\text{ph}} = \text{Rotor turns/Statorturns} = 1/4$$

$$E_2 = (1/4) \times E_{1\text{ph}} = 230.94/4 = 57.735 \text{ V}$$

$$N_s = 120f/P = 120 \times 50 / 4 = 1500 \text{ r.p.m.}$$

i) At start, $s=1$

$$T_{\text{st}} = (k E_2^2 R_2) / (R_2^2 + (X_2)^2) \quad \text{where } k = 3 / (2 \pi n_s)$$

$$n_s = N_s/60 = 1500/60 = 25 \text{ r.p.s.}$$

$$k = 3 / (2\pi \times 25) = 0.01909$$

$$T_{\text{st}} = (0.01909 \times 57.735^2 \times 0.01) / (0.01^2 + 0.1^2) = \mathbf{63.031 \text{ N-m}}$$

ii) Slip at which maximum torque occurs is,

$$S_m = R_2/X_2 = 0.01/0.1 = 0.1$$

$$\% S_m = 0.1 \times 100 = \mathbf{10\%}$$

iii) Speed at which maximum torque occurs is speed corresponding to,

$$N = N_s(1 - s_m) = 1500(1 - 0.1) = \mathbf{1350 \text{ r.p.m.}}$$

5. Draw torque slip characteristics curve and explain

TORQUE-SLIP CHARACTERISTICS

As the induction motor is loaded from no load to full load, its speed decreases hence slip increases. Due to the increased load, motor has to produce more torque to satisfy load demand. The torque ultimately depends on slip. The behaviour of motor can be easily judged by sketching a curve obtained by plotting torque produced against slip of induction motor.

“The curve plotting torque against slip from $s=1$ (at start) to $s=0$ (at synchronous speed) is called slip characteristic of the induction motor.” We have seen that for a constant supply voltage, E_2 is also constant. So we can write torque equations as, *obtained by torque-*

$$T \propto \frac{s R_2}{R_2^2 + (sX_2)^2}$$

To judge the nature of torque-slip characteristics let us divide the slip range ($s=0$ to $s=1$) into two regions and analyse them independently.

Low slip region:

In low slip region, 's' is very very small. Due to this, the term $(sX_2)^2$ is so small as compared to R_2^2 that it can be neglected.

$$T \propto \frac{s R_2}{R_2^2} \propto s$$

... As R_2 is constant.

Hence in low slip region torque is directly proportional to slip. So as load increases, speed decreases, increasing the slip. This increases the torque which satisfies the load demand. Hence the graph is straight line in nature. At $N=N_s, s=0$ hence $T=0$. As no torque is generated at $N=N_s$, motor stops if it tries to achieve the synchronous speed. Torque increases linearly in this region, of low slip values.

High slip region:

In this region, slip is high, i.e. slip value is approaching to 1. Here it can be assumed that the term R_2^2 is very very small as compared to $(sX_2)^2$. Hence neglecting from the denominator, we get

$$T \propto \frac{s R_2}{(sX_2)^2} \propto \frac{1}{s} \quad \text{where } R_2 \text{ and } X_2 \text{ are constants.}$$

So in high slip region torque is inversely proportional to the slip. Hence its nature is like rectangular hyperbola. Now when load increases, load demand increases but speed decreases. As speed decreases, slip increases. In high slip region as $T \propto 1/s$, torque decreases as slip increases.

But torque must increase to satisfy the load demand. As torque decreases, due to extra loading effect, speed further decreases and slip further increases. Again torque decreases as $T \propto 1/s$ hence same load acts as an extra load due to reduction in torque produced. Hence speed further drops. Eventually motor comes to stand still condition. The motor cannot continue to rotate at any point in this high slip region. Hence this region is called unstable region of operation.

So torque-slip characteristics has two parts,


- Straight line called stable region of operation
- Rectangular hyperbola called unstable region of operation.

Stable operation:

In low slip region, as load increases, slip increases and torque also increases linearly. Every motor has its own limit to produce torque. The maximum torque, the motor can produce as load increases is T_m which occurs at $s = s_m$. So linear behavior continues till $s = s_m$. So range $s = 0$ to $s = s_m$ is called **low slip region**, known as stable region of operation. Motor always operates at a point in this region.

Unstable operation:

If load is increased beyond this limit, motor slip acts dominantly pushing motor into high slip region. Due to unstable conditions, motor comes to standstill condition at such a load. Hence i.e. maximum torque which motor can produce is also called **breakdown torque or pullout torque**. And range $s = s_m$ to $s = 1$ is called high slip region which is rectangular hyperbola, called **unstable region of operation**. Motor cannot continue to rotate at any point in this region. At $s = 1$, $N = 0$ i.e. start, motor produces a torque called **starting torque** denoted as T_{st} .

TORQUE -SLIP CHARACTERISTICS CURVE:***Torque-slip characteristics***

When the load on the motor increases, the torque produced increases as speed decreases and slip increases. The increase in torque demand is satisfied by drawing motor current from the supply. The load which motor can drive safely while operating continuously and due to such load, the current drawn is also within safe limits is called full load condition of motor. When current increases, due to heat produced the temperature rises. The safe limit of current is that which when drawn for continuous operation of motor, produces a temperature rise well within the limits. Such a full load point is shown on the torque-slip characteristics curve as T_{FL} .

The interesting thing is that the load on the motor can be increased beyond point C till maximum torque condition. But due to high current and hence high temperature rise there is possibility of damage of winding insulation, if motor is operated for long time duration in this region i.e. from point C to B. But motor can be used to drive loads more than full load, producing torque up to maximum torque for short duration of time. Generally full load torque is less than the maximum torque.

So region OC up to full load condition allows motor operation continuously and safely from the temperature point of view. While region CB is possible to achieve in practice but only for short duration of time and not for continuous operation of motor. This is the difference between full load torque and the maximum or breakdown torque. The breakdown torque is also called **stalling torque**.

6. Explain in detail about the losses and efficiency of an three phase induction motor**LOSSES IN INDUCTION MOTOR:**

The various power losses in an induction motor can be classified as,

- **Constant losses**
- **Variable losses**

Constant losses:

Constant losses in three phase induction motor can be further classified as

- **Core losses**

- Mechanical losses.

Core losses:

Core losses occur in stator core and rotor core. These are also called **iron losses** as the stator and rotor core are made up of iron material (Silicon steel). These losses are subdivided into

- Eddy current losses
- Hysteresis losses

The eddy current losses are minimized by using laminated construction while hysteresis losses are minimized by selecting high grade silicon steel as the material for stator and rotor. The iron losses depend on the frequency. The stator frequency is always supply frequency hence stator iron losses are dominant. As against this in rotor circuit, the frequency is very small which is slip times the supply frequency. Hence rotor iron losses are very small and hence generally neglected, in the running condition.

Mechanical losses:

The mechanical losses include frictional losses at the bearings and windings losses. The friction changes with speed but practically the drop in speed is very small hence these losses are assumed to be the part of constant losses.

Variable losses:

Variable

losses include the copper losses in stator and rotor winding due to current flowing in the winding. As current changes as load changes, these losses are said to be variable losses. Generally stator iron losses are combined with stator copper losses at a particular load to specify total stator losses at particular load condition.

Rotor copper loss = $P_{cu} = 3 I_{2r}^2 R_2$ ----- analysed separately

Where, I_{2r} = Rotor current per phase at a particular load

R_2 = Rotor resistance per phase


EFFICIENCY OF AN INDUCTION MOTOR:

“The ratio of output power available at the shaft (P_{out}) and the net electrical power input (P_{in}) to the motor is called as overall efficiency of an induction motor.”

$$\text{Efficiency} = \frac{\text{Output Power (P}_{out}\text{)}}{\text{Input Power (P}_{in}\text{)}}$$

$$\% \text{ Efficiency} = \frac{\text{Output Power (P}_{out}\text{)}}{\text{Input Power (P}_{in}\text{)}} * 100$$

MAXIMUM EFFICIENCY:



The maximum efficiency occurs when variable losses become equal to constant losses. When the motor is on no load, current drawn by the motor is small. Hence efficiency is low. As load increases, current increases so copper losses also increase. When such variable losses achieve the same value as that of constant losses, efficiency attains its maximum value. If load is increased further, variable losses become greater than constant losses, hence deviating from the condition for maximum, efficiency starts decreasing.

7. What is meant by starter? Why starter is necessary for an induction motor to start and give its

types

STARTER:

Starter is a device which is used to start the three phase induction motor

NECESSITY OF STARTER:

In a three phase induction motor, the magnitude of an induced e.m.f. in the rotor circuit depends on the slip of the induction motor. This induced e.m.f. effectively decides the magnitude of the rotor current. The rotor current in the running condition is given by,

$$I_{2r} = \frac{sE_2}{\sqrt{R_2^2 + (sX_2)^2}}$$

But at start, the speed of the motor is zero and slip is at its maximum i.e. unity. So the magnitude of rotor induced e.m.f. is very large at start. As rotor conductors are short circuited, the large induced e.m.f. circulates very high current through rotor at start.

The condition is exactly similar to a transformer with short circuited secondary. Such a transformer when excited by a rated voltage circulates very high current through short circuited secondary. As secondary current is large, the primary also draws very high current from the supply.

Similarly in a three phase induction motor, when rotor current is high, consequently the stator draws a very high current from the supply. Similarly in a three phase induction motor, when rotor current is high, consequently the stator draws a very high current from the supply. This current can be of the order of 5 to 8 times the full load current, at start.

Due to such heavy inrush current at start there is possibility of damage of the motor winding. Similarly such sudden inrush of current causes large line voltage drop. Thus other appliances connected to the same line may be subjected to voltage spikes which may affect their working. To avoid such effects, it is necessary to limit the current drawn by the motor at start.

“The starter is a device which is basically used to limit high starting current by supplying reduced voltage to the motor at the time of starting”.

Such a reduced voltage is applied only for short period and once rotor gets accelerated, full normal rated voltage is applied.

In three phases induction motors the starters operations are

- To limit the starting current
- To protect against overloading loading
- To protect against low voltage situations
- To protect against single phasing

The induction motor having rating below 5h.p. can withstand starting currents hence such motors can be started directly on line. But such motors also need overload, single phasing and low voltage protection which is provided by a starter. Thus all the three phase induction motors need some or the other type of starter.

TYPES OF STARTERS:

The various types of starters for three phase induction motor is given by

- Stator resistance starter
- Autotransformer starter
- Star-delta starter
- Rotor resistance starter
- Direct on line starter


8. Explain the starting method of cage induction motors (APRIL/2014)

(or)

Explain any two starting methods of three phase induction motor. (NOV/2013)

1. STATOR RESISTANCE STARTER:

In order to apply the reduced voltage to the stator of the induction motor, three resistances are added in series with each phase of the stator winding. Initially the resistances are kept in maximum in the circuit. Due to its large voltage gets dropped across the resistances. Hence a reduced voltage gets applied to the stator which reduces the high starting current. The schematic diagram showing stator resistances is shown below figure.



Stator Resistance starter

When the motor starts running, the resistances are gradually cut-off from the stator circuit. When the resistances are entirely removed from the stator circuit i.e. the rheostat is in RUN position then rated voltage gets applied to the stator. Motor runs with normal speed.

Advantage:

- Simple in construction
- Cheap
- Can be used for both star and delta connected stator


Disadvantage:

- Large power losses due to resistances.
- The starting torque of the motor reduces due to reduced voltage applied to the stator.

9. Explain the operation of star delta starter and auto transformer starter used for three phase induction motor. (NOV/2012)

2. AUTO TRANSFORMER STARTER:


A three phase star connected autotransformer can be used to reduce the voltage applied to the stator. Such a starter is called an autotransformer starter. The schematic diagram of autotransformer starter is shown in the below figure.



Autotransformer starter

It consists of a suitable changeover switch. When the switch is in the start position, the stator winding is supplied with reduced voltage. This can be controlled by tapings provided with autotransformer. The reduction in applied voltage by the fractional percentage tapping's x , used for an

autotransformer is shown in the below figure.



Use of autotransformer to reduce voltage at start

When motor gathers 80% of the normal speed, the changeover switch is thrown into run position. Due to this, rated voltage gets applied to stator winding. The motor starts rotating with normal speed. Changing of switch is done automatically by using relays.

Advantages:

- The power loss is much less in this type of starting.
- Can be used for both star and delta connected motors.


Disadvantage:

- It is expensive than stator resistance starter.

3. STAR-DELTA STARTER:

It is commonly used starter in three phase induction motor. It uses triple pole double throw (TPDT) switch. The switch connects the stator winding in star at start. Hence per phase voltage gets reduced by the factor $1/\sqrt{3}$. Due to this reduced voltage, the starting current is limited.

When the switch is thrown on other side, the winding gets connected in delta, across the supply. So it gets normal rated voltage. The windings are connected in delta when motor gathers sufficient speed. The arrangement of star-delta starter is shown in the below figure.



Star-delta starter

The operation of the switch can be automatic by using relays which ensure that motor will not start with the switch in Run position.

Advantages:


- Thecheapest starter
- Maintenancefreeoperation

Disadvantages:

- Itissuitablefor normal deltacconnectedmotorsandthefactorby whichvoltagechangesis $1/\sqrt{3}$ whichcannotbe changed.

4. ROTORRESISTANCESTARTER:

To limit the rotor current which consequently reduce the current drawn by the motor from the supply, the resistance can be inserted in the rotor circuit at start. This addition of the resistance in rotor in the form of three phase star connected rheostat.



Rotorresistancestarter

The external resistance is inserted in each phase of the rotor winding through slip ring and brush assembly. Initially maximum resistance is in the circuit. As motor gathers speed, the resistance is gradually cut-off. The operation may be manual or automatic. We have seen that the starting torque is proportional to the rotor resistance.

Advantages:

- Improved starting torque for the motor

Disadvantages:

- Can be used only for slip ring induction motors


5. DIRECT ON LOAD LINE STARTER (D.O.L.):

In case of small capacity motor having rating less than 5 h.p., the starting current is not very high and such motors can withstand such starting current without any starter. Thus there is no need to reduce applied voltage, to control the starting current. Such motors use a type of starter which is used to connect stator directly to the supply lines without any reduction in voltage. Hence the starter is known as direct on line starter.

Though this starter does not reduce the applied voltage, it is used because it protects the motor from various severe abnormal conditions like over loading, low voltage, single phasing.

The NO contact is normally open and NC is normally closed. At start, NO is pushed for a fraction of second due to which coil gets energized and attracts the contactor. So stator directly gets supply. The additional contact provided, ensures that as long as supply is ON, the coil gets supply and keeps contactor in ON position. When NC is pressed, the coil circuit gets opened due to which coil gets de-energized and motor gets switched OFF from the supply.

Under over load condition, current drawn by the motor increases due to which is an excessive heat produced, which increases temperature beyond limit. Thermal relays get opened due to high temperature, protecting the motor from overload conditions.



Direct Online starter

10. Discuss the various schemes used for speed control of 3 phase induction motor. (APRIL/2012)

SPEED CONTROL OF THREE PHASE INDUCTION MOTOR

A three phase induction motor is practically a constant speed motor like a D.C. shunt motor. But the speed of D.C. shunt motor can be varied smoothly just by using simple rheostats. This maintains the speed regulation and efficiency of D.C. shunt motor. But in case of three phase induction motor it is very difficult to achieve smooth speed control. And if the speed control is achieved by some means, the performance of the induction motor in terms of its power factor, efficiency etc. gets adversely affected.

For the induction motor we know that,

$$N = N_s(1 - s)$$

From this expression it can be seen that the speed of induction motor can be changed either by changing its synchronous speed or by changing the slip s . Similarly torque produced in case of three phase induction motor is given by,

$$T \propto \frac{sE_2^2 R_2}{R_2^2 + (sX_2)^2}$$

So as the parameters like R_2, E_2 are changed then to keep the torque constant for constant load condition, motor reacts by change in its slip. Effectively its speed changes.

METHODS OF SPEED CONTROL:

The speed of the induction motor can be controlled by basically two methods:

- From stator side
- From rotor side

From stator side:

- Supply frequency control to control N_s , called V / f control.
- Supply voltage control.
- Controlling number of stator poles to control N_s .
- Adding rheostats in stator circuit.

From rotor side:

- Adding external resistance in the rotor circuit.
- Cascade control.
- Injecting slip frequency voltage into the rotor circuit.

STATORSIDE CONTROL:

1. Supply Frequency Control or V/ f Control

The synchronous speed is given by,

$$N_s = 120f / P$$

Thus by controlling the supply frequency smoothly, the synchronous speed can be controlled over a wide range. This gives smooth speed control of an induction motor.

But the expression for the air gap flux is given by,

$$\Phi_g = \frac{1}{4.44 K_1 T_{ph1}} \left\{ \frac{V}{f} \right\}$$

This is according to the e.m.f. equation of a transformer where,

K_1 = Stator winding constant


T_{ph1} = Stator turns per phase

V = Supply voltage

f = Supply frequency

From this expression that if the supply frequency f is changed, the value of air gap flux also gets affected. This may result into saturation of stator and rotor cores. Such saturation leads to the sharp increase in the (magnetization) no load current of the motor. Hence it is necessary to maintain air gap flux constant when supply frequency is changed.

To achieve this, it can be seen from the above expression that along with f , V also must be changed so as to keep (V/f) ratio constant. This ensures constant air gap flux giving speed control without affecting the performance of the motor. Hence this method is called **V / f control**.




Electronic scheme for V/f control

Hence in this method, the supply to the induction motor required is variable voltage variable frequency supply and can be achieved by an electronics scheme using converter and inverter circuitry.

The normal supply available is constant voltage constant frequency A.C. supply. The converter converts this supply into a D.C. supply. This D.C. supply is then given to the inverter. The inverter is a device which converts D.C. supply to variable voltage variable frequency A.C. supply which is required to keep V/f ratio constant. By selecting the proper frequency and maintaining V / f constant, smooth speed control of the induction motor is possible.

If the normal working frequency then the below figures show the torque-slip characteristics for the frequency $f_1 > f$ and $f_2 < f$ i.e. for frequencies above and below the normal frequency.



Torque-slip characteristics with variable and constant (V/f)

Disadvantages:

- The supply obtained cannot be used to supply other devices which require constant voltage. Hence an individual scheme for a separate motor is required
- This method is costly

2. Supply (or) Stator Voltage Control

We know that,

$$T \propto \frac{s E_2^2 R_2}{R_2 + (s X_2)}$$

Now E_2 , the rotor induced e.m.f. at standstill depends on the supply voltage V .


$$E_2 \propto V$$

Also for low slip region, which is operating region of the induction motor, $(sX_2)^2 \ll R_2$ and hence can be neglected.

$$T \propto s V^2 R_2 / R_2^2 + s V^2 \text{ for constant } R_2^2$$

Now if supply voltage is reduced below rated value, as per above equation torque produced also decreases. But to supply the same load it is necessary to develop same torque hence value of slip increases so that torque produced remains same. Slip increase means motor reacts by running at lower speed, to decrease in supply voltage. So motor produces the required load torque at a lower speed. The speed-torque characteristics for the motor using supply voltage control are shown in the below figure.

But in this method, due to reduction in voltage, current drawn by the motor increases. Large change in voltage for small change in speed is required is the biggest disadvantage.



Speed-torque curves for motor with voltage control

Disadvantage:

Due to increased current, the motor may get overheated. Additional voltage changing equipment is necessary. Hence this method is rarely used in practice.

Due to reduced voltage, E_2 decreases, decreasing the value of maximum torque too.

Application:

Motors driving fan type of loads use this method of speed control.

3. Controlling Number of Poles

In this method poles are changed to control the speed of three phase induction motors. In this method, it is possible to have one, two or four speeds in steps, by the changing the number of stator poles. A continuous smooth speed control is not possible by this method.


The stator poles can be changed by following methods:

- (i). *Consequent poles method*
- (ii). *Multiple stator winding method*
- (iii). *Pole amplitude modulation method.*

(i). Consequent Poles Method


In this method, connections of the stator winding are changed with the help of simple switching. Due to this, the number of stator poles gets changed in the ratio 2:1. Hence either of the two synchronous speeds can be selected. Consider the pole formation due to single phase of a three phase winding, as shown in the below figure. There are three tapping points to the stator winding. The supply is given to two of them and third is kept open.

It can be seen that current in all the parts of stator coil is flowing in one direction only. Due to this, 8 poles get formed as shown in the below figure. So synchronous speed possible with this arrangement with 50 Hz frequency is $N_s = 750$ r.p.m.




Pole winding

If the two terminals to which supply was given either are joined together and supply is given between this common point and the open third terminal, the poles are formed as in below figure.



Pole Winding

It can be seen that the direction of current through remaining two. Thus upward direction is forming say S pole and downward say N. It can be observed that in this case only 4 poles are formed. So the synchronous speed possible is 1500 r.p.m. for 50 Hz frequency.




Thus series/parallel arrangements of coils can produce the poles in the ratio 2:1. But the speed change is in steps and smooth speed control is not possible. Similarly the method can be used only for the squirrel cage type motors as squirrel rotor adjusts itself to same number of poles as stator which is not the case in slip ring induction motor.

(ii). Multiple Stator Winding Method

In this method instead of one winding, two separate stator windings are placed in the stator core. The windings are placed in the stator slots only but are electrically isolated from each other. Each winding is divided into coils to which, pole changing with consequent poles, facility is provided. Thus giving supply to one of the two windings and using switching arrangement, two speeds can be achieved. Same is true for other stator winding. So in all four different speeds can be obtained.

4. Adding Rheostats in Stator Circuit



The reduced voltage can be applied to the stator by adding the rheostats in the stator circuit. The part of the voltage gets dropped across the resistances and reduced voltage gets applied across the stator. The reduction in stator voltage causes reduction in the speed. The rheostats can be varied as per the required change in speed. But the entire line current flows through the rheostats and hence there are large power losses. The method is not efficient from speed control point of view hence used as a starter rather than as a speed control method.

ROTOR SIDE CONTROL:


1. Adding External Resistance in Rotor Circuit

$$T \propto \frac{s E_2^2 R_2}{R_2 + (s X_2)}$$

For low slip region ($s (s X_2)^2 \ll R_2$) and can be neglected and for constant supply voltage is also constant

$$T \propto \frac{sR_2}{R_2} \propto \frac{s}{R_2}$$

Thus if the rotor resistance is increased, the torque produced decreases. But when the load on the motor is same, motor has to supply same torque as load demands. So motor reacts by increasing its slip to compensate decreases in T due to R_2 and maintain the load torque constant. So due to that additional rotor resistance R_2 , motor slip increases i.e. the speed of the motor decreases. Thus by increasing the rotor resistance R_2 , speeds below normal value can be achieved. Another advantage of this method is that the starting torque of the motor increases proportional to rotor resistance. This method is rarely used in the practice due to the following disadvantages.



Torque-speed curves for rotor resistance control

Disadvantages:

- The large speed changes are not possible. This is because for large speed change, large resistance is required to be introduced in rotor which causes large rotor copper loss due to reduce the efficiency.
- The method cannot be used for the squirrel cage induction motors.
- The speeds above the normal values cannot be obtained.
- Large power losses occur due to large loss.
- Sufficient cooling arrangements are required which make the external rheostats bulky and expensive.
- Due to large power losses, efficiency is low.


11. Explain about the concatenation connection of three phase induction motor with neat diagram

2. Cascade Control:

Cascade control is also called **Concatenation** or **Tandem operation** of the induction motors. Here, two induction motors are mounted on the same shaft. One of the two motors must be of slip ring type which is called main motor. The second motor is called auxiliary motor. The arrangement of this cascade method is shown below.

The auxiliary motor can be slip ring or squirrel cage type. The stator of the main motor is connected to the three phase supply. While the supply of the auxiliary motor is derived as a slip frequency from the slip rings of the main motor. This is called **cascading** of the motors. If the torque produced by both acts in the same direction, cascading is called **cumulative cascading**. If the torque produced is in opposite direction, cascading is called **differential cascading**.

Let, P_A = Number of poles of main motor
 P_B = Number of poles of auxiliary motor
 f = Supply frequency



Cascade control of two induction motor

$$N_{sA} = \frac{120 f}{P_A}$$

N = Speed of the set

The speed N is same for both the motors as motors are mounted on the same shaft.

$$s_A = \frac{N_{sA} - N}{N_{sA}}$$

Now f_A = Frequency of rotor induced e.m.f. of motor A

$\therefore f_A = s_A f \dots$ as $f_r = s f$

Now on no load, the speed of the rotor B i.e. N is almost equal to its synchronous speed N_{sB} .

$$\therefore N_{sB} = N$$

$$\therefore N = 120 \left(\frac{N_{sA} - N}{N_{sA}} \right) \times \frac{f}{P_B}$$

$$\therefore N = \frac{120 f}{P_B} \times \left[1 - \frac{N}{N_{sA}} \right]$$

$$\therefore N = \frac{120 f}{P_B} \times \left[1 - \frac{N}{\left(\frac{120 f}{P_A} \right)} \right]$$

$$\therefore N = \frac{120 f}{P_B} \left[1 - \frac{N P_A}{120 f} \right]$$

$$\therefore N \left[1 + \frac{P_A}{P_B} \right] = \frac{120 f}{P_B}$$

$$\therefore \boxed{N = \frac{120 f}{P_A + P_B}}$$

If by interchanging any two terminals of motor B, the reversal of direction of rotating magnetic field of B is achieved then the set runs as differentially cascaded set. And in such a case effective number of poles is $P_A - P_B$.

Thus in cascade control, four different speeds are possible as,

➤ With respect to synchronous speed of A independently,

$$N_{sA} = \frac{120 f}{P_A}$$

- With respect to synchronous speed of B independently with main motor is disconnected and B is directly connected to supply,

$$N_{sB} = \frac{120f}{P_B}$$

- Running set as cumulatively cascaded with,

$$N = \frac{120f}{P_A + P_B}$$

- Running set as differentially cascaded with,

$$N = \frac{120f}{P_A - P_B}$$

Disadvantages:

- It requires two motors which makes the set expensive.
- Smooth speed control is not possible.
- Operation is complicated.
- The starting torque is not sufficient to start the set.
- Set cannot be operated if $P_A = P_B$.


3. Injecting Slip-Frequency E.M.F. into Rotor Circuit:

In this method, a voltage is injected in the rotor circuit. The frequency of rotor circuit is a slip frequency and hence the voltage to be injected must be at a slip frequency. It is possible that the injected voltage may oppose the rotor induced e.m.f. or may assist the rotor induced e.m.f. If it is in the phase opposition, effective rotor resistance increases. If it is in the phase of rotor induced e.m.f., effective rotor resistance decreases. Thus by controlling the magnitude of the injected e.m.f., rotor resistance and effectively speed can be controlled.

Practically two methods are available which use this principle. These methods are,

- *Kramer system*
- *Scherbius system*

KRAMER SYSTEM:



Kramer system

This system consists of main induction motor M, speed of which is to be controlled. A DC motor & rotary converter is used. The slip rings of main motor are connected to AC side of rotary converter.

The D.C side of rotary converter feeds a D.C shunt motor commutator, which is directly connected to the shaft of the main motor. Rotary converter converts the low-slip frequency A.C power into D.C power supplied from main line so that its speed derives from a fixed value only to the extent

of the slip of auxiliary induction motor. Both dc motor & rotary converter are excited from a separate DC supply. The variable resistance introduces the field circuit of a DC motor, which act as a field regulator. The speed of the set is controlled by varying the field of DC motor with rheostat R when the field rheostat is changed, the back E.M.F of motor change. Thus D.C voltage at the commutator changes, this changes D.C voltage on the D.C side of rotary converter. Now Rotary converter has a fixed ratio between its A.C & D.C side voltages. Thus Voltage on its A.C side also changes. This A.C voltage is given to the slip ring of that main motor. So the voltage injected in the rotor of main motor which produces the required speed control.

Application:


- Very large motors (above 4000kw) such a steel rolling mills use this type.

Advantages:

- Smooth speed control is possible.
- Wide range of speed control is possible.
- Design of rotary converter is independent of speed control required.
- If rotary converter is excited, it draws leading current & hence power factor can be improved.

SCHERBIUS SYSTEM:

This is another method for controlling a large size induction motors. The slip energy is not converted into DC and then fed to a DC motor; rather it is fed directly to a special three phase (or) six phase AC commutator motor called a Scherbius machine. The poly phase winding of machine C is supplied with the low-frequency output of machine M through a regulating transformer RT. The commutator motor C is a variable-speed motor and its speed is controlled by either varying the tapplings on RT or by adjusting the position of brushes on C.



12. Explain about the construction and working operation of an single phase induction motor

SINGLE PHASE INDUCTION MOTOR

Single phase motors are the most familiar of all electric motors because they are extensively used in home appliances, shops, offices due to availability for single phase supply worldwide very easy. These AC motors are called single phase induction motors. The power rating of such motors is very small. Some of them are even fractional horsepower motors, which are used in applications like small toys, small fans, hair dryers etc.

CONSTRUCTION OF SINGLE PHASE INDUCTION MOTORS

Single phase induction motor has basically two main parts.

- **Stator** (*stationary parts in motor*)
- **Rotor** (*rotating parts in motor*)

STATOR:


The stator has laminated construction, made up of stampings. The stampings are slotted on its inner periphery to carry the winding called stator winding or main winding. This is excited by a single phase A.C supply. The laminated construction keeps iron losses (or) core loss to minimum. The stampings are made up of high graded silicon steel which minimizes the hysteresis loss. The stator winding is wound for certain definite number of poles means when excited by single phase AC supply, stator produces the magnetic field which creates the effect of certain definite number of poles. The number of poles for which stator winding is wound, decides the synchronous speed of the motor. The synchronous speed is denoted as N_s and it has a fixed relation with supply frequency f and number of poles P . The relation is given by,

$$N_s = \frac{120 f}{P}$$

The induction motor never rotates with the synchronous speed but rotates at a speed which is slightly less than the synchronous speed.

ROTOR:


The rotor construction is of squirrel cage type as that of in three phase motor. Rotor consists of un-insulated copper or aluminium bars, placed in the slots. The bars are permanently shorted at both the ends with the help of conducting rings called *end rings*. The entire structure looks like a cage hence called squirrel cage rotor. The construction and symbol is shown in the below figure.



As the bars are permanently shorted to each other, the resistance of the entire rotor is very very small. The air gap between stator and rotor is kept uniform and as small as possible. The main feature of this rotor is that it automatically adjusts itself for same number of poles as that of the stator winding.

WORKING PRINCIPLE OF SINGLE PHASE INDUCTION MOTOR

The schematic representation of single phase induction motor is shown in the below figure. For the motoring action, there must exist two fluxes which interact with each other to produce the torque. In the single phase induction motor, single phase AC supply is given to the stator winding. The stator winding carries an alternating current which produces the flux which is also alternating in nature. This flux is called *main flux*.



This flux links with the rotor conductors and due to transformer action, e.m.f. gets induced in the rotor. The induced e.m.f. drives current through the rotor as rotor circuit is closed circuit. This rotor current produces another flux called **rotor flux** required for the motoring action. Thus second flux is produced according to induction principle due to induced e.m.f. hence the motor is called **induction motor**.

As against this in DC motor a separate supply is required to armature to produce armature flux. This is an important difference between DC motor and an induction motor. Another important difference between the two is that the DC motors are self-starting while **single phase induction motors are not self-starting**.

13. Explain the operation of single phase induction motor on the basis of double field revolving theory with neat sketch. (11) (NOV/2014)

DOUBLE REVOLVING FIELD THEORY

According to double revolving field theory, any alternating quantity can be resolved into two rotating components which rotate in opposite directions and each having magnitude as half of the maximum magnitude of the alternating quantity. In case of single phase induction motors, the stator winding produces an alternating magnetic field having maximum magnitude of Φ_{1m} .


According to double revolving field theory, consider the two components of the stator flux, each having magnitude half of maximum magnitude of stator flux i.e. $(\Phi_{1m}/2)$. Both these components are rotating in opposite directions at the synchronous speed N_s which is dependent on frequency and stator poles.

Let

Φ_f is forward component rotating in anticlockwise direction

Φ_b is the backward component rotating in clockwise direction.

The resultant of these two components at any instant gives the instantaneous value of the stator flux at the instant. So resultant of these two is the original stator flux.



Stator flux and its two components

The above figure shows the stator flux and its two components Φ_f and Φ_b . At start both the components are shown opposite to each other in the above figure (a). Thus the resultant $\Phi_R = 0$. This is nothing but the instantaneous value of the stator flux at start. After 90° as shown in the above figure (b), the two components are rotated in such a way that both are pointing in the same direction. Hence the resultant Φ_R is the algebraic sum of the magnitudes of the two components.

$$\text{So } \Phi_R = (\Phi_{1m}/2) + (\Phi_{1m}/2) = \Phi_{1m}$$


This is nothing but the instantaneous value of the stator flux at $\theta = 90^\circ$ as shown in the above figure (c). Thus continuous rotation of the two components gives the original alternating stator flux.

Both the components are rotating and hence get cut by the motor conductors. Due to cutting of flux, e.m.f. gets induced in rotor which circulates rotor current. The rotor current produces rotor flux. This flux interacts with forward component Φ_f to produce a torque in one particular direction say anticlockwise direction. While rotor flux interacts with backward component Φ_b to produce a torque in the clockwise direction. So if anticlockwise torque is positive then clockwise torque is negative.

At start, these two torques are equal in magnitude but opposite in direction. Each torque tries to rotate the rotor in its own direction. Thus **net torque experienced by the rotor is zero at start.** And hence these single phase induction motors are not self-starting.

TORQUE SPEED CHARACTERISTICS

The two oppositely directed torques and the resultant torque can be shown effectively with the help of torque-speed characteristics. It is shown in the below figure.




Torque-speed characteristics

It can be seen that at start $N = 0$ and at that point resultant torque is zero. So single phase motors are not self-starting. However if the rotor is given an initial rotation in any direction, the resultant average torque increases in the direction in which rotor initially rotated. And motor starts rotating in that direction. But in practice it is not possible to give initial torque to rotor externally hence some modifications are done in the construction of single phase induction motors to make them self-starting.

MAKING SELF-STARTING SINGLE PHASE MOTOR:

The single-phase induction motor is not self-starting and it is undesirable to give mechanical spinning of the shaft to start it. To make a single-phase induction motor self-starting, a revolving stator magnetic field is required. This may be achieved by converting a single-phase supply into two-phase supply through the use of an additional winding. When the motor attains sufficient speed, the starting means (i.e., additional winding) may be removed depending upon the type of the motor. As a matter of fact, single-phase induction motors are classified and named according to the method employed to make them self-starting.


The construction of two phase motor and two fluxes having phase difference of between them are shown in the below.




More the phase difference angle α , more is starting torque produced.

PRODUCTION OF ROTATING FIELD FROM TWO-PHASE SUPPLY:

It will now be shown that when stationary coils, wound for two phases are supplied by two phase supply respectively, a uniformly-rotating (or revolving) magnetic flux of constant value is produced.



The principle of a two phase, 2-pole stator having two identical windings, 90° spaces apart, is illustrated in the above figure. The flux due to the current flowing in each phase winding is assumed sinusoidal and is represented in the above figure. The assumed positive directions of fluxes are shown in above figure.



Let Φ_1 and Φ_2 be the instantaneous values of the fluxes set up by the two windings. The resultant flux Φ_r at any time is the vector sum of these two fluxes (Φ_1 and Φ_2) at that time. We will consider conditions at intervals of $1/8^{\text{th}}$ of a time period i.e. at intervals corresponding to angles of $0^\circ, 45^\circ, 90^\circ, 135^\circ$ and 180° . It will be shown that resultant flux Φ_r is constant in magnitude i.e. equal to Φ_m – the maximum flux due to either phase and is making one revolution/cycle. In other words, it means that the resultant flux rotates synchronously.

- When $\theta = 0^\circ$ i.e., corresponding to point 0 in the above figure, $\Phi_1 = 0$, but Φ_2 is maximum i.e. equal to Φ_m and negative. Hence, resultant fluxes $\Phi_R = \Phi_m$ and, being negative, is shown by a vector pointing downwards [Figure (i)].
- When $\theta = 45^\circ$ i.e. corresponding to point 1 in above figure. At this instant, $\Phi_1 = \Phi_m / \sqrt{2}$ and is positive; $\Phi_2 = \Phi_m / \sqrt{2}$ but is still negative. Their resultant, as shown in figure (ii), is $\phi_r = \sqrt{\left[\left(\frac{\phi_m}{\sqrt{2}}\right)^2 + \left(\frac{\phi_m}{\sqrt{2}}\right)^2\right]} = \Phi_m$ although this resultant has shifted 45° clockwise.
- When $\theta = 90^\circ$ i.e. corresponding to point 2 in above figure. Here $\Phi_2 = 0$, but $\Phi_1 = \Phi_m$ and is positive. Hence, $\Phi_r = \Phi_m$ and has further shifted by an angle of 45° from its position by 90° from its original position as shown in figure (iii).
- When $\theta = 135^\circ$ i.e. corresponding to point 3 in above figure. Here, $\Phi_1 = \Phi_m / \sqrt{2}$ and is positive, $\Phi_2 = \Phi_m / \sqrt{2}$ and is also positive. The resultant $\Phi_r = \Phi_m$ and has further shifted clockwise by another 45° , as shown in figure (iv).
- When $\theta = 180^\circ$ i.e. corresponding to point 4 in above figure Here, $\Phi_1 = 0, \Phi_2 = \Phi_m$ and is positive. Hence, $\Phi_r = \Phi_m$ and has shifted clockwise by another 45° or has rotated through an angle of 180° from its position at the beginning as shown in figure (v).

Hence, we conclude

- That the magnitude of the resultant flux is constant and is equal to Φ_m , the maximum flux due to either phase.
- That the resultant flux rotates at synchronous speed given by $N_s = 120f / P$ rpm.

14. What are the types of single phase induction motor? Explain about any two types of single phase induction motor

TYPES OF SINGLE PHASE INDUCTION MOTOR


- Split-phase motors
- Capacitor start motors
- Capacitor start Capacitor run motors
- Shaded-pole motors

1. SPLIT-PHASE INDUCTION MOTOR

Construction:

The stator of a split-phase induction motor is provided with an **auxiliary winding S** in addition to the **main or running winding M**. The starting winding is located 90° electrical from the main winding and operates only during the short period when the motor starts up. A centrifugal switch is connected in series with starting winding.

The two windings are so designed that the **starting winding S** has **high resistance** and **Low reactance** while the **main winding M** has relatively **low resistance** and **large reactance** as shown in the schematic connections. Consequently, the currents flowing in the two windings have a reasonable phase difference (25° to 30°) as shown in the phasor diagram.



Operation

When the two stator windings are energized from a single-phase supply, the main winding carries current I_m while the starting winding carries current I_s . Since main winding is made highly inductive while the starting winding highly resistive, the currents I_m and I_s have a reasonable phase angle (25° to 30°) between them as shown in Phasor

diagram. Consequently, a weak revolving field approximating that of a 2-phase machine is produced which starts the motor.

The starting torque is given by;


$$T_s = k I_m I_s \sin \alpha$$

Where, k is a constant whose magnitude depends upon the design of the motor.

When the motor reaches about 75% of synchronous speed, the centrifugal switch opens the circuit of the starting winding. The motor then operates as a single-phase induction motor and continues to accelerate till it reaches the normal speed. The normal speed of the motor is below the synchronous speed and depends upon the load on the motor.

Characteristics

- The starting torque is 1.5 to 2 times the full-load torque (i.e., starting current is 6 to 8 times the full-load current.)
- Due to their low cost, split-phase induction motors are most popular single-phase motors in the market.



- Since the starting winding is made of fine wire, the current density is high and the winding heats up quickly. If the starting period exceeds 5 seconds, the winding may burn out unless the motor is protected by built-in thermal relay. This motor is, therefore, suitable where starting periods are short.
- An important characteristic of these motors is that they are essentially constant-speed motors. The speed variation is 2-5% from no-load to full-load.
- The power rating of such motors generally lies between 60 W and 250 W

Applications:


- Fans
- Washing machines
- Oil burners
- Centrifugal pumps
- Small machine tools etc.

15. Explain why the single phase induction motors are not self-starting? Describe the operation of capacitor start and run motors in detail. (APRIL/2014)

2. CAPACITOR-START MOTOR

Construction:

The capacitor-start motor is identical to a split-phase motor except that the starting winding has many turns as the main winding. Moreover, a capacitor C is connected in series with the starting winding as shown in below figure. The value of capacitor is chosen so that I_s leads I_m by about 80° (i.e., $\alpha \approx 80^\circ$) which is considerably greater than 25° found in split-phase motor.



Operation:

A single phase supply is given to the two winding of stator. The starting current I_s leads the line voltage due to the presence of a capacitor in series with starting winding. The running current I_m lags the line voltage. The phase displacement between these two currents is approximately equal to 90° during starting period. Consequently, starting torque ($T_s = k I_m I_s \sin \alpha$) is much more than that of a split-phase motor. Again, the starting winding is opened by the centrifugal switch when the motor attains about 75% of synchronous speed. The motor then operates as a single-phase induction motor and continues to accelerate till it reaches the normal speed.

Characteristics:

- Although starting characteristics of a capacitor-start motor are better than those of a split-phase motor, both machines possess the same running characteristics because the main windings are identical.
- The phase angle between the two currents is about 80° compared to about 25° in a split-phase motor. Consequently, for the same starting torque, the current in the starting winding is only about half that in a split-phase motor. Therefore, the starting winding of a capacitor start motor heats up less quickly and is well suited to applications involving either frequent or prolonged starting periods.
- Capacitor-start motors are used where high starting torque is required and where the starting period may be long enough to drive.
- The power rating of such motors lies between 120 W and 7500 W

Applications:


- Compressors
- Large fans
- Pumps
- Refrigerators
- High inertial loads

3. CAPACITOR-START CAPACITOR-RUN MOTOR

Construction and Operation:


This motor is identical to a capacitor-start motor except that starting winding is not opened after starting so that both the windings remain connected to the supply when running as well as at starting. Two designs are generally used.

- In one design, a single capacitor C is used for both starting and running as shown in figure (i). This design eliminates the need of a centrifugal switch and at the same time improves the power factor and efficiency of the motor.
- In the other design, two capacitors C_1 and C_2 are used in the starting winding as shown in figure (ii). The smaller capacitor C_1 required for optimum running conditions is permanently connected in series with the starting winding. The much larger capacitor C_2 is connected in parallel with C_1 for optimum starting and remains in the circuit during starting. The starting capacitor C_1 is disconnected when the motor approaches about 75% of synchronous speed. The motor then runs as a single-phase induction motor.



Characteristics:

- The starting winding and the capacitor can be designed for perfect 2-phase operation at any load. The motor then produces a constant torque and not a pulsating torque as in other single-phase motors.
- Because of constant torque, the motor is vibration free and can be used in places where silence is important.



Applications:

- Hospitals
- Studios


4. **SHADED POLE INDUCTION MOTOR**

Construction:


This type of motor consists of a squirrel cage rotor and stator consisting of salient poles i.e. projected poles. The poles are shaded i.e. each pole carries a copper band on one of its unequally divided parts called shading band. Figure (a) shows 4 pole shaded pole construction while figure (b) shows a single pole consisting of copper shading band.

Operation:

When single phase AC supply is given to the stator winding, due to shading provided to the poles, a rotating magnetic field is generated.




The current carried by the stator winding is alternating and produces alternating flux. The waveform of the flux is shown in the below figure. The distribution of this flux in the pole area is greatly influenced by the role of copper shading band. Consider the three instants say t_1, t_2 and t_3 during first half cycle of the flux as shown, in the figure.



Case (i) $t = t_1$

At instant $t=t_1$, rate of rise of current and hence the flux is very high. Due to the transformer action, large e.m.f. gets induced in the copper shading band. This circulates current through shading band as it is short circuited, producing its own flux. According to **Lenz's law**, the direction of this current is so as to oppose the cause i.e. rise in current. Hence shading ring flux is opposing to the main flux. Hence there is crowding of flux in non-shaded part while weakening of flux in shaded part. Overall magnetic axis shifts in non-shaded part as shown in the below figure (i).



Production of rotating magnetic field


Case (ii) $t=t_2$

At instant $t=t_2$, rate of rise of current and hence the rate of change of flux is almost zero as flux almost reaches to its maximum value. So $d\Phi/dt=0$. Hence there is very little induced e.m.f. in the shading ring. Hence the shading ring flux is also negligible, hardly affecting the distribution of the main flux. Hence the main flux distribution is uniform and magnetic axis lies at the centre of the pole faces as shown in the figure (ii).

Case (iii) $t=t_3$

At the instant $t=t_3$, the current and the flux is decreasing. The rate of decrease is high which again induces a very large e.m.f. in the shading ring. This circulates current through the ring which produces its own flux. Now direction of the flux produced by the shaded ring current is so as to oppose the cause which is decrease in flux. So it opposes the decrease in flux means its direction is same as that of main flux, strengthening it. So there is crowding of flux in the shaded part as compared to non-shaded part. Due to this the magnetic axis shifts to the middle of the shaded part of the pole. This is shown in the figure (iii).

This sequence keeps on repeating for negative half cycle too. Consequently this produces an effect of rotating magnetic field, the direction of which is from non-shaded part of the pole to the shaded part of the pole. Due to this, motor produces the starting torque is low which is about 40 to 50% of the full load torque for this type of motor. The torque speed characteristics are shown in the below figure.



Torque-speed characteristics of shaded pole motor

Due to absence of centrifugal switch the construction is simple and robust but this type of motor has a lot of lamination as:

- The starting torque is poor.
- The power factor is very low.
- Due to I^2R , copper losses in the shading ring the efficiency are very low.
- The speed reversal is very difficult. To achieve the speed reversal, the additional set of

shading rings is required. By opening one set and closing the other, direction can be reversed but the method is complicated and expensive.

- The size and power rating of these motors is very small. These motors are usually available in a range of 1/300 to 1/20 kW.
- These motors are cheap but have very low starting torque, low power factor and low efficiency

Application

- Advertising displays,
- Film projectors,
- Record players,
- Gramophones,
- Hairdryers,
- Photo copying machines

16. Explain construction and operation of stepper motor. (NOV/2013)

(or)

Explain in detail about different modes of operation of stepper motor. (NOV/2012)

STEPPER MOTOR

A step or stepping motor converts electronic pulses into proportionate mechanical movement. Each revolution of the stepper motor's shaft is made up of a series of discrete individual steps. A step is defined as the angular rotation produced by the output shaft each time the motor receives a step pulse. These types of motors are very popular in digital control circuits, such as robotics, because they are ideally suited for receiving digital pulses for step control. Each step causes the shaft to rotate a certain number of degrees.

A step angle represents the rotation of the output shaft caused by each step, measured in degrees. The below figure illustrates a simple application for a stepper motor. Each time the controller receives an input signal, the paper is driven a certain incremental distance. In addition to the paper drive mechanism in a printer, stepper motors are also popular in machine tools, process control systems, tape and disk drive systems, and programmable controllers.

Stepper Motors Working

Stepper motors consist of rotating shaft with permanent magnet attached is called rotor and the stationary housing containing the coil-wound poles is called stator (i.e. electromagnets on the stationary portion that surrounds the motor).


Types of Stepper Motors

There are basically three types of stepping motors;

- Variable reluctance stepper motor
- Permanent magnet stepper motor
- Hybrid stepper motor


Full Stepping

The below figure illustrates a typical step sequence for a two phase motor. In Step 1 phase A of a two phase stator is energized. This magnetically locks the rotor in the position shown, since unlike poles attract. When phase A is turned off and phase B is turned on, the rotor rotates 90° clockwise. In Step 3, phase B is turned off and phase A is turned on but with the polarity reversed from Step 1. This causes another 90° rotation. In Step 4, phase A is turned off and phase B is turned on, with polarity reversed from Step 2. Repeating this sequence causes the rotor to rotate clockwise in 90° steps.



One Phase ON


The stepping sequence illustrated in the above figure is called “one phase on” stepping. A more common method of stepping is “two phase on” where both phases of the motor are always energized. However, only the polarity of one phase is switched at a time, as shown in figure. With two phases on stepping the rotor aligns itself between the “average” north and “average” south magnetic poles. Since both phases are always on, this method gives 41.4% more torque than “one phase on” stepping, but with twice the power input.



Two Phase ON

Half Stepping

The motor can also be “half stepped” by inserting an off state between transitioning phases. This cuts a stepper’s full step angle in half. For example, a 90° stepping motor would move 45° on each half step, in the below figure. However, half stepping typically results in a 15% - 30% loss of torque depending on step rate when compared to the two phase on stepping sequence. Since one of the windings is not energized during each alternating half step there is less electromagnetic force exerted on the rotor resulting in a net loss of torque.



Half Stepping

There are several types of stepper motors. 4-wire stepper motors contain only two electromagnets; however the operation is more complicated than those with three or four magnets, because the driving circuit must be able to reverse the current after each step. For our purposes, we will be using a 6-wire motor.

Unlike our example motors which rotated 90 degrees per step, real-world motors employ a series of mini-poles on the stator and rotor to increase resolution. Although this may seem to add more complexity to the process of driving the motors, the operation is identical to the simple 90 degree motor we used in our example. An example of a multi pole motor can be seen in the below figure. In position 1, the north pole of the rotor's permanent magnet is aligned with the south pole of the stator's electromagnet. Note that multiple positions are aligned at once. In position 2, the upper electromagnet is deactivated and the next one to its immediate left is activated, causing the rotor to rotate a precise amount of degrees. After eight steps the sequence repeats

17. Explain the construction and working of AC series motor. (APRIL/2013) (APRIL/2012)

SINGLE PHASE A.C. SERIES MOTOR


In a normal DC motor if direction of both field and armature current is reversed, the direction of torque remains unchanged. So when normal DC series motor is connected to an AC supply, both field and armature current get reversed and unidirectional torque gets produced in the motor hence motor can work on AC. supply. But performance of such motor is not satisfactory due to the following reasons

- There are tremendous eddy current losses in the yoke and field cores, which causes overheating.
- Armature and field winding offer high reactance to AC due to which operating power factor is very low.
- The sparking at brushes is a major problem because of high voltage and current induced in the short circuited armature coils during the commutation period.

Some modifications are required to have the satisfactory performance of DC series motor on AC supply, when it is called AC series motor. The modification are:

- To reduce the eddy current losses, yoke and pole core construction is laminated.
- The power factor can be improved by reducing the magnitudes of field and armature reactance.

Field reactance can be decreased by reducing the number of turns. But this reduces the field flux. But this reduction in flux ($N \propto 1/\Phi$), increases the speed and reduce the torque. To keep the torque same it is necessary to increase the armature turns proportionately. This increases the armature inductance. Now to compensate for increased armature flux which produce severe armature reaction, it is necessary to use compensating winding. The flux produced by this winding is opposite to that produced by armature and effectively neutralizes the armature reaction. If such a compensating winding is connected in series with the armature, the motor is said to be 'conductively compensated'. For motors to be operated on AC and DC both, the compensation should be conductive. If compensating winding is short circuited on its self, the motor is said to be 'inductively compensated'. In this compensating winding acts as a secondary of transformer and armature as its primary. The ampere turns produced by compensating winding neutralise the armature ampere turns..




(a) *Conductively Compensated motor*, (b) *Inductively Compensated Motor*

To reduce the induced e.m.f. due to transformer action in the armature coils while commutation period, the following measures are taken:

- The flux per pole is reduced and numbers of poles are increased.
- The frequency of supply used is reduced.
- Preferably single turn armature coils are used.

The characteristics of such motor are similar to that of DC series motor. The torque varies as square of the armature current and speed varies inversely as the armature current. The speed of such motor can be dangerously high on no load condition and hence it is always started with some load. Starting torque produced is high which the full load torque is 3 to 4 times. The speed-torque characteristics of such type of motors is as shown in the Figure



Torque Speed Characteristics

Applications

- Because of high starting torque it is used in electric traction
- Hoists
- Locomotives

Reference:

- *B.L.Theraja&A.K.Theraja, A Textbook of Electrical Technology: AC and DCMachines, Volume - II, 23rd Edition, S. Chand & Company, New Delhi, 2012*
- *U. A. Bakshi, M. V. Bakshi, Electrical Machines-II, Second Edition, Technical Publications*